



Date: ☒ Wednesday, 9/13/2006 4:31:58 PM
User: ☒ Kim Johnston

Process Sheet

Customer :	CU-DAR001 Dart Helicopters Services	Drawing Name :	SHORT STEP INSTALLATION KIT
Job Number :	28535		
Estimate Number :	10542		
P.O. Number :	N/A	Part Number :	K591113
This Issue :	9/13/2006	S.O. No. :	N/A
Prsht Rev. :	NC	Drawing Number :	D350-591 REV F PG17
First Issue :	N/A	Project Number :	N/A
Previous Run :	27760	Drawing Revision :	F
	Type :	Material :	N/A
	SMALL /MED FAB	Due Date :	10/6/2006
Written By :			
Checked & Approved By :			
Comment :	Est : C 04 11.09 Reformat KJ/JLM		

Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	D2171	Clamp
-----	-------	-------



Comment: Qty.: 2.0000 Each(s)/Unit Total : 8.0000 Each(s)

Clamp

Pick:

Qty	Part Number	Description	Batch
<input checked="" type="checkbox"/> 2	D2171	Clamp	B27244

2.0	D2182B	Neoprene Cushion-.750 bl
-----	--------	--------------------------



Comment: Qty.: 0.5833 f(s)/Unit Total : 2.3332 f(s)

Neoprene Cushion-.750 bl

Pick:

Qty	Part Number	Description	Batch
<input checked="" type="checkbox"/> 7	D2182B	Cushion	B28042

3.0	D2274	Radius Block
-----	-------	--------------



Comment: Qty.: 4.0000 Each(s)/Unit Total : 16.0000 Each(s)

Radius Block

Pick:

Qty	Part Number	Description	Batch
<input checked="" type="checkbox"/> 4	D2274	Radius Block	B28824

4.0	D23623	Step Support Bracket
-----	--------	----------------------



Comment: Qty.: 1.0000 Each(s)/Unit Total : 4.0000 Each(s)

Step Support Bracket

Pick:

Qty	Part Number	Description	Batch
<input checked="" type="checkbox"/> 1	D2362-3	Support Bracket	B28550

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 9/13/2006 4:31:58 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SHORT STEP INSTALLATION KIT

Job Number: 28535

Part Number: K591113

Job Number:



Seq. #:

Machine Or Operation:

Description :

5.0

D2856400

Abrasion Strip



Comment: Qty.: 0.6000 f(s)/Unit Total : 2.4000 f(s)

Abrasion Strip

Pick:

Qty	Part Number	Description	Batch
✓ 7.2" (QTY 1)	D2856-400	Abrasion Strip	B28258

6.0

AN337A

Bolt



Comment: Qty.: 2.0000 Each(s)/Unit Total : 8.0000 Each(s)

Bolt

Pick:

Qty	Part Number	Description	Batch
✓ 2	AN3-37A	Bolt	M1478

7.0

AN420A

Bolt



Comment: Qty.: 4.0000 Each(s)/Unit Total : 16.0000 Each(s)

Bolt

Pick:

Qty	Part Number	Description	Batch
✓ 4	AN4-20A	Bolt	M16895

8.0

AN422A

Bolt



Comment: Qty.: 1.0000 Each(s)/Unit Total : 4.0000 Each(s)

Bolt

Pick:

Qty	Part Number	Description	Batch
✓ 1	AN4-22A	Bolt	M17280

9.0

AN960JD10

Washer



Comment: Qty.: 4.0000 Each(s)/Unit Total : 16.0000 Each(s)

Washer

Pick:

Qty	Part Number	Description	Batch
✓ 4	AN960JD10	Washer	M100743 -

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes ☒ No ☐ DQA: ☒ Date: 26/10/27
 QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Wednesday, 9/13/2006 4:31:58 PM
User: Kim Johnston

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: SHORT STEP INSTALLATION KIT

Job Number: 28535

Part Number: K591113

Job Number:



Seq. #:

Machine Or Operation:

Description :

10.0

AN960JD416

Washer



Comment: Qty.: 6.0000 Each(s)/Unit Total : 24.0000 Each(s)

Washer

Pick:

Qty	Part Number	Description	Batch
✓ 6	AN960JD416	Washer	M102339

11.0

MS21042L3

Nut



Comment: Qty.: 2.0000 Each(s)/Unit Total : 8.0000 Each(s)

Nut

Pick:

Qty	Part Number	Description	Batch
✓ 2	MS21042L3	Nut	M101390

12.0

MS21042L4

Nut



Comment: Qty.: 5.0000 Each(s)/Unit Total : 20.0000 Each(s)

Nut

Pick:

Qty	Part Number	Description	Batch
✓ 5	MS21042L4	Nut	M19099

PC 6/10/28 (4)

13.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT KITS 100% FOR COMPLETENESS

PC 06/10/25 (4)

14.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: 4

PC 4/12

15.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

PC 06/10/25 (4)

Job Completion



W 10.10.25

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

5. PARTS LIST

Qty -111A	Qty -113	Qty -115	Qty -117A	Qty -119	Qty -133	Part Number	Description
X						D350-591-111A	<i>Heli-Access-Step</i> ™, Long Step – High Skid
	X					D350-591-113	<i>Heli-Access-Step</i> ™, Short Step – High Skid
		X				D350-591-115	<i>Heli-Access-Step</i> ™, Short Step – Low Skid
			X			D350-591-117A	<i>Heli-Access-Step</i> ™, Pre-Flight Step
				X		D350-591-119	<i>Heli-Access-Step</i> ™, Long Step – Low Skid
					X	D350-591-133	<i>Heli-Access-Step</i> ™, Aft Maintenance Step
	1					D2310	STEP ASSEMBLY (HIGH-SHORT)
1						D2311	STEP ASSEMBLY (HIGH-LONG)
		1				D2354	STEP ASSEMBLY (LOW-SHORT)
				1		D2355	STEP ASSEMBLY (LOW-LONG)
					1	D2946-041	STEP ASSEMBLY (MAINTENANCE)
4	2	2	2	2		D2171	CLAMP
4	2	2	2	2		D2182B035	CUSHION
					4	D2230-1	MOUNTING LUG
					4	D2230-3	MOUNTING LUG
8	4	4	4	4		D2274	RADIUS BLOCK
			1			D2362-041	SUPPORT BRACKET
2	1			1		D2362-3	SUPPORT BRACKET
		1				D2362-5	SUPPORT BRACKET
2	1	1	1	1	2	D2856-400-720	ABRASION STRIP
					1	D2945	MOUNTING PLATE
2	2	2		2		AN3-37A	BOLT
					2	AN4-7A	BOLT
					4	AN4-11A	BOLT
					8	AN4-14A	BOLT
8	4	4	4	4		AN4-20A	BOLT
1	1	1		1		AN4-22A	BOLT
4	4	4		4		AN960JD10	WASHER
10	6	6	4	6	14	AN960JD416	WASHER
2	2	2		2		MS21042L3	NUT
9	5	5	4	5	14	MS21042L4	NUT

Qty -121	Qty -122	Qty -123	Qty -124	Part Number	Description
X				D350-591-121	<i>Heli-Access-Step</i> ™, Short Step – High Skid, LH
	X			D350-591-122	<i>Heli-Access-Step</i> ™, Short Step – High Skid, RH
		X		D350-591-123	<i>Heli-Access-Step</i> ™, Short Step – Low Skid, LH
			X	D350-591-124	<i>Heli-Access-Step</i> ™, Short Step – Low Skid, RH
1				D2351-041	STEP ASSEMBLY (HIGH-SHORT, LH)
	1			D2351-042	STEP ASSEMBLY (HIGH-SHORT, RH)
		1		D2356-041	STEP ASSEMBLY (LOW-SHORT, LH)
			1	D2356-042	STEP ASSEMBLY (LOW-SHORT, RH)
1	1	1	1	D2230-1	MOUNTING LUG
1	1	1	1	D2230-3	MOUNTING LUG
1	1	1	1	D2856-400-720	ABRASION STRIP
2	2	2	2	AN3-37A	BOLT
3	3	3	3	AN4-13A	BOLT
4	4	4	4	AN960JD10	WASHER
6	6	6	6	AN960JD416	WASHER
2	2	2	2	MS21042L3	NUT
3	3	3	3	MS21042L4	NUT

HOP COPY
 RETURN TO
 ENGINEERING
 UNCONTROLLED COPY
 SUBJECT TO AMENDMENT
 WITHOUT NOTICE
 WORK ORDER
 NO. 28535

• COPYRIGHT © 1993 BY DART AEROSPACE LTD. •
 THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED
 OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: F
 Date: 04.03.02